

AVIA PROPELLER Ltd Beranových 65/666 199 00 Praha 9 Czech Republic	SERVICE LETTER SL- 9B	DOA No. EASA.21J.072
---	--	-----------------------------

AV-803-1-K-C PROPELLER SERIES REPLACEMENT OF CLAMPS AND COUNTERWEIGHTS

1. Effectivity

AV-803-1-K-C propellers from S/No.070003 to S/No.080042 (propellers manufactured from March 2007 to September 2008).

2. Description

Base on a production deviation Avia Propeller prescribes a replacement of the clamps and counterweights incl. connecting bolts of AV-803-1-K-C propellers mentioned in section 1.

The clamps and counterweights which are installed on the affected propellers must be sent to producer for the inspection or repair.

The clamps and counterweights can be installed back on the propeller after inspection. The connecting bolts between clamp and counterweight must be replaced by new ones.



The clamps and counterweights are possible to be replaced by clamps with counterweights designed as one-piece part.

3. Requirements

Replacement has to be carried out only by Avia Propeller service personnel.

4. Record

Replacement of the parts has to be recorded into the propeller Logbook.

Office of Airworthiness Zbyněk Tvrđík  Date : January 19, 2009	Issue Michal Rout  Date : January 19, 2009		Page : 1 Pages : 1
---	---	--	-----------------------